



FLL Landside Advisory


Please Post and Disseminate to All Airport Employees and Applicable Vendors

ISSUED: December 30, 2021

FLL21-12-69L

REVISION: N/A

GAS PIPE UPGRADE SOUTHSIDE RENTAL CAR CENTER



LOCATION: Rental Car Center, Southside

SCHEDULE: Monday, January 3, 2022 from 8:00 A.M. to 5:00 P.M.

WORK PERFORMED: TECO Gas contractor, MEARS, will be installing new gas piping in the grass swale located north of Terminal Drive.

IMPACT:

- Vehicles will be redirected to use the north lane adjacent to the RCC.
- Maintenance of traffic include signage and flagman guiding drivers to available areas.
- Vehicles will not be allow to turn southbound just East of the RCC from East Perimeter Road.

Report issues to Airport Operations Control Center 954-359-1201